

TABLE 1  
WASTE DISPOSAL  
CARTER COLOR COAT REMOVAL ACTION  
TDD NO: S05-0808-003  
DETROIT, MICHIGAN

Manifest Number	Date	Content	Volume (yd <sup>3</sup> )	Disposal Facility
80	11/6/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
81	11/6/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
82	11/6/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
83	11/6/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
84	11/6/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
85	12/18/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
86	12/18/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
87	12/18/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
88	12/18/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
89	12/18/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
90	12/18/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
91	12/18/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
92	12/18/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
93	12/18/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
94	12/23/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
95	12/23/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
96	12/23/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
97	12/23/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
98	12/23/2008	Wood Block	40	Carleton Farms Landfill New Boston, MI
<b>Non-hazardous waste Roll Off Box</b>				
1	12/18/2008	Wood Block	20	Carleton Farms Landfill New Boston, MI
<b>Non-hazardous water (Truck ramp)</b>				
004703226JJK	1/5/2009	Liquid	9,200 gallons	EQ Detroit, Inc. Detroit, MI
004703222JJK	1/5/2009	Liquid	3,400 gallons	EQ Detroit, Inc. Detroit, MI
<b>Hazardous waste liquid</b>				
004682713JJK	1/5/2009	AST liquid	600 Gallons	EQ Detroit, Inc. Detroit, MI
<b>PCB Ballasts</b>				
004682712JJK	1/5/2009	PCB Ballast	7- 55 gallon drums	Wayne Disposal Belleville, MI

*italics = estimated*



**ENCLOSURE 3**  
**PHOTOGRAPHIC LOG**  
**(Sixteen Pages)**





<b>Photograph No.:</b> 1	<b>Orientation:</b> North
<b>TDD Number:</b> S05-0808-003	<b>Date:</b> September 22, 2008
<b>Photographer:</b> K. Campbell, START	<b>Site Name:</b> Carter Color Coat Removal Site
<b>Location:</b> Detroit, Wayne County, Michigan	
<b>Subject:</b> Asbestos contractor conducted an asbestos removal on the first floor of discarded insulation left by vandals. .	



<b>Photograph No.:</b> 2	<b>Orientation:</b> West
<b>TDD Number:</b> S05-0808-003	<b>Date:</b> September 24, 2008
<b>Photographer:</b> K. Campbell, START	<b>Site Name:</b> Carter Color Coat Removal Site
<b>Location:</b> Detroit, Wayne County, Michigan	
<b>Subject:</b> U.S. EPA contractor removing PCB contaminated wood block flooring located on the first floor of the building.	





<b>Photograph No.:</b> 3	<b>Orientation:</b> South
<b>TDD Number:</b> S05-0808-003	<b>Date:</b> September 25, 2008
<b>Photographer:</b> K. Campbell, START	<b>Site Name:</b> Carter Color Coat Removal Site
<b>Location:</b> Detroit, Wayne County, Michigan	
<b>Subject:</b> First floor area where the PCB-contaminated wood block floor was removed. The removed blocks and debris was stockpiled awaiting disposal.	



<b>Photograph No.:</b> 4	<b>Orientation:</b> Northeast
<b>TDD Number:</b> S05-0808-003	<b>Date:</b> September 27, 2008
<b>Photographer:</b> K. Campbell, START	<b>Site Name:</b> Carter Color Coat Removal Site
<b>Location:</b> Detroit, Wayne County, Michigan	
<b>Subject:</b> First floor stockpile of PCB-contaminated wood block floor and debris.	





<b>Photograph No.:</b> 5	<b>Orientation:</b> East
<b>TDD Number:</b> S05-0808-003	<b>Date:</b> September 29, 2008
<b>Photographer:</b> K. Campbell, START	<b>Site Name:</b> Carter Color Coat Removal Site
<b>Location:</b> Detroit, Wayne County, Michigan	
<b>Subject:</b> U.S. EPA contractor removing low hanging metal in preparation for wood block removal with skid steers.	




<b>Photograph No.:</b> 6	<b>Orientation:</b> South
<b>TDD Number:</b> S05-0808-003	<b>Date:</b> September 30, 2008
<b>Photographer:</b> K. Campbell, START	<b>Site Name:</b> Carter Color Coat Removal Site
<b>Location:</b> Detroit, Wayne County, Michigan	
<b>Subject:</b> Wood block stockpile area outside the building.	






<b>Photograph No.:</b> 7	<b>Orientation:</b> West
<b>TDD Number:</b> S05-0808-003	<b>Date:</b> October 1, 2008
<b>Photographer:</b> K. Campbell, START	<b>Site Name:</b> Carter Color Coat Removal Site
<b>Location:</b> Detroit, Wayne County, Michigan	
<b>Subject:</b> U.S. EPA contractor attaching skid steer platform to crane for lifting to second floor.	



<b>Photograph No.:</b> 8	<b>Orientation:</b> Northwest
<b>TDD Number:</b> S05-0808-003	<b>Date:</b> October 1, 2008
<b>Photographer:</b> K. Campbell, START	<b>Site Name:</b> Carter Color Coat Removal Site
<b>Location:</b> Detroit, Wayne County, Michigan	
<b>Subject:</b> Loaded skid steer being lifting to second floor by crane.	





<b>Photograph No.:</b> 9	<b>Orientation:</b> South
<b>TDD Number:</b> S05-0808-003	<b>Date:</b> October 1, 2008
<b>Photographer:</b> K. Campbell, START	<b>Site Name:</b> Carter Color Coat Removal Site
<b>Location:</b> Detroit, Wayne County, Michigan	
<b>Subject:</b> U.S. EPA contractor preparing to off load skid steer onto second floor.	



<b>Photograph No.:</b> 10	<b>Orientation:</b> Southeast
<b>TDD Number:</b> S05-0808-003	<b>Date:</b> October 1, 2008
<b>Photographer:</b> K. Campbell, START	<b>Site Name:</b> Carter Color Coat Removal Site
<b>Location:</b> Detroit, Wayne County, Michigan	
<b>Subject:</b> U.S. EPA contractor driving skid steer off platform onto second floor.	